# DUNE WALKWAY INVENTORY

Seabrook, NH

# Amesbury Street

Walkway Phys	sical Condition Good Condition
Road to Beach	433 ft
Walkway Length	363 ft
Sand path to Beach	70 ft
Walkway Width	4.0 ft
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>
Surface Condition	Solid/Minimal tilting
Dune Slope	Medium
Attached pathways	
Benches	4
Additional Features	Railings & viewing platform



## Andover Street

Walkway Physical Condition		Fair Condition
Road to Beach		
Walkway Length	467 ft	
Sand path to Beach	70 ft	
Walkway Width	4.0 ft	
Walkway Material	<ul> <li>Asphalt apron</li> <li>Composite &amp; Woo planks</li> </ul>	oden
Surface Condition	Some tilting, loose bo overgrown brush imp walkway	
Dune Slope	Medium	
Attached pathways	3	
Benches	4	
Additional Features	Railings and benches	3



## Ashland Street

Walkway Physical Condition		Good Condition
Road to Beach		

NUAU LU DEACH	
Walkway Length	82 ft
Sand path to Beach	70 ft
Walkway Width	5.3 ft
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>
Surface Condition	Solid/Minimal tilting
Dune Slope	Medium
Attached pathways	
Benches	4
Additional Features	Wooden posts separating walkway from driveway





## **Chelmsford Street**

Walkway Physical Condition Good		
Road to Beach	433 ft	
Walkway Length	495 ft	
Sand path to Beach	87 ft	
Walkway Width	4.0 ft	
Walkway Material	<ul> <li>Asphalt apron</li> <li>Composite &amp; Wooden planks</li> </ul>	
Surface Condition	Solid/Minimal tilting	
Dune Slope	Medium	
Attached pathways		
Benches		
Additional Features	Railings & viewing platform	





#### **Dracut Street**

Walkway Physical Condition		Good Condition
Road to Beach	433 ft	
Walkway Length	410 ft	
Sand path to Beach	88 ft	
Walkway Width	4.0 ft	
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>	
Surface Condition	Solid/Minimal tiltir	ıg
Dune Slope	Flat	
Attached pathways	2	
Benches		
Additional Features		



## **Groveland Street**

Walkway Phys	sical Condition Fair	
Road to Beach		
Walkway Length	185 ft	
Sand path to Beach	81ft	
Walkway Width	4.0 ft	
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>	
Surface Condition	Some loose boards, minor tilting	
Dune Slope	Medium	
Attached pathways		
Benches		
Additional Features		



## Haverhill Street

Walkway Physical Condition Go	
Road to Beach	433 ft
Walkway Length	308 ft
Sand path to Beach	77 ft
Walkway Width	8.0 ft
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>
Surface Condition	Solid/Minimal tilting
Dune Slope	Medium
Attached pathways	
Benches	
Additional Features	



## Hudson Street

Walkway Physical Condition		Good Condition
Road to Beach		
Walkway Length	420 ft	
Sand path to Beach	60 ft	
Walkway Width	4.0 ft	
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>	
Surface Condition	Solid/Minimal tilting toward crest of the dune	
Dune Slope	Medium	
Attached pathways		
Benches		
Additional Features	birdhouses	



#### Lawrence Street

Walkway Physical Condition Good	
Road to Beach	
Walkway Length	415 ft
Sand path to Beach	89 ft
Walkway Width	4.0 ft
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>
Surface Condition	Solid/Minimal tilting
Dune Slope	Medium
Attached pathways	2
Benches	
Additional Features	Nonslip material





Lowell Street		
Walkway Physical Condition Good		
Road to Beach		
Walkway Length	430 ft	
Sand path to Beach	70 ft	
Walkway Width	4.0 ft	
Walkway Material	<ul> <li>Asphalt apron</li> <li>Composite &amp; Wooden planks</li> </ul>	
Surface Condition	Solid/Minimal tiltin	g
Dune Slope	Flat	
Attached pathways	2	
Benches		
Additional Features	Viewing point with	benches



# Merrimack Street

Walkway Phys	sical Condition Fair
Road to Beach	
Walkway Length	380 ft
Sand path to Beach	94 ft
Walkway Width	4.0 ft
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>
Surface Condition	Loose boards
Dune Slope	Flat / windy
Attached pathways	3 with others seen adjacent
Benches	1
Additional Features	



## Methuen Street

Walkway Phys	sical Condition	Good Condition
Road to Beach		
Walkway Length	453 ft	
Sand path to Beach	89 ft	
Walkway Width	4.0 ft	
Walkway Material	<ul> <li>Asphalt apron</li> <li>Composite &amp; V planks</li> </ul>	/ooden
Surface Condition	Solid	
Dune Slope	Flat	
Attached pathways	2	
Benches	2	
Additional Features	Railings, detached of wooden planks walkway	





# Nashua Street

Walkway Physic	al Condition Good
Road to Beach	
Walkway Length	520 ft
Sand path to Beach	71 ft
Walkway Width	3.1 ft
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>
Surface Condition	Minor tilting, some loose boards
Dune Slope	Medium
Attached pathways	1
Benches	
Additional Features	





# Newbury Street

Walkway Phys	sical Condition	Good Condition
Road to Beach		
Walkway Length	102 ft	
Sand path to Beach	136 ft	
Walkway Width	4.0 ft	
Walkway Material	<ul> <li>Asphalt apron</li> <li>Composite &amp; V planks</li> </ul>	Vooden
Surface Condition	Newer	
Dune Slope	Medium	
Attached pathways		
Benches		
Additional Features	Lights along walkw	vay







New Hampshire Street		
Walkway Phys	sical Condition	Good Condition
Road to Beach		
Walkway Length	239 ft	
Sand path to Beach	NA – all sand	
Walkway Width		
Walkway Material	Sand path	
Surface Condition	Flat	
Dune Slope	None	
Attached pathways	3	
Benches	2	
Additional Features		



## **Tilton Street**

Walkway Phys	sical Condition Good Condition
Road to Beach	
Walkway Length	83 ft
Sand path to Beach	80 ft
Walkway Width	8.0 ft
Walkway Material	<ul><li>Asphalt apron</li><li>Composite &amp; Wooden planks</li></ul>
Surface Condition	Solid
Dune Slope	NA not on a dune
Attached pathways	None
Benches	1
Additional Features	



Walkway Physical Condition       Good         Condition       Condition         Road to Beach       Condition
Road to Beach
Walkway Length 500 ft
Sand path to Beach 80 ft
Walkway Width 4 ft
<ul> <li>Asphalt apron</li> <li>Walkway Material</li> <li>Composite &amp; Wooden planks</li> </ul>
Surface Condition Solid/Minimal tilting
Dune Slope Medium
Attached pathways 2
Benches 3

